

AD-A099 699

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. CRANBERRY LAKE DAM, (NJ00325) DELA--ETC(U)

MAR 81 P YU


DACW61-79-C-0011

UNCLASSIFIED

DAEN/NAP-53842/NJ00325-81/ NL

1 OF 1
AD-A
10/16/81

END
DATE
FILMED
6-81
DTIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

LEVEL

(P)

AD A 099 699

DELAWARE RIVER BASIN,
LUBBERS RUN, SUSSEX COUNTY
NEW JERSEY.

CRANBERRY LAKE DAM NJ 00325

DTIC
ELEC
JUN 3 1981

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
DACW 61-79-C-0011



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

AD A 099 699

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

Rept. no. DAEN/NAP - 53842/NJ 00325-81/03
MARCH 1981

81 6 03 093

(10) Peter/Yu

1. REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM	
2. REPORT NUMBER DAEN/NAP-53842/NJ00325-81/03	3. GOVT ACCESSION NO. AD-A099699	4. RECIPIENT'S CATALOG NUMBER	
5. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program, Cranberry Lake Dam, (NJ00325) Delaware River, Sussex County, N.J. Bass, Lubbers Run		6. TYPE OF REPORT & PERIOD COVERED 9 FINAL rept.	
7. AUTHOR(s) Yu, Peter Sussex County, New Jersey, Phase I Inspection Report		8. PERFORMING ORG. REPORT NUMBER 15 CONTRACT OR GRANT NUMBER(s) DACW61-79-C-0011	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Langan Engineering Assoc. Inc. 990 Clifton Ave. Clifton, NJ 07013		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CN029 Trenton, NJ 08625		12. REPORT DATE March 1981	
13. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106		14. NUMBER OF PAGES 45	
(12) 85		15. SECURITY CLASS. (of this report) Unclassified	
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.			
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) C JUN 3 1981 D			
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Embankments Visual Inspection Structural Analysis National Dam Safety Program Spillways Outlet pipes Seepage Riprap Lubbers Run, N.J. Cranberry Lake Dam, N.J.			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.			

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**



IN REPLY REFER TO
NAPEN-N

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-20 & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

22 MAY 1981

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Cranberry Lake Dam in Sussex County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Cranberry Lake Dam, a high hazard potential structure, is judged to be in poor overall condition. The spillway is considered seriously inadequate since a flow equivalent to 29 percent of the Probable Maximum Flood (PMF) would cause the dam to be overtopped. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard of loss of life downstream from the dam. To ensure adequacy of the structure, the following actions, as a minimum, are recommended.

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures and studies within three months from the date of approval of this report. Within three months of the consultant's findings remedial measures to ensure spillway adequacy should be initiated. In the interim, a detailed emergency operation plan and warning system should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

APPROVED FOR PUBLIC RELEASE.
DISTRIBUTION UNLIMITED.

NAPEN-N

Honorable Brendan T. Byrne

b. The following remedial measures should be initiated within three months from the date of approval of this report:

(1) Investigate the operating condition of the spillway sluice gate and the low level outlet pipe and valve. Repair and modify if necessary.

(2) Remove obstructions and debris in the discharge and downstream channel and provide means to prevent future accumulation of material.

(3) Investigate the backwater effect of the downstream abandoned railroad embankment, modify the outlet facilities or remove the embankment if necessary.

(4) Properly fill the existing animal burrow and provide means to prevent future animal burrowing in the embankment.

c. The following remedial measures should be initiated within six months from the date of approval of this report:

(1) Repair eroded areas of the embankment.

(2) Repair dislodged upstream riprap.

(3) Repair the cracked and spalled concrete of the spillway structure.

(4) Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundations, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and what modifications may be required to achieve such safety margins.

d. The following remedial actions should be initiated within one year from the date of approval of this report:

(1) Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

(2) Properly remove all trees from the dam embankment and provide adequate filter coverage on the downstream face to prevent any piping which may occur as a result of future root decay.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

NAPEN-N

Honorable Brendan T. Byrne

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,

James G. Ton

JAMES G. TON
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Copies furnished:
Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief
Bureau of Flood Plain Regulation
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

CRANBERRY LAKE DAM (NJ00325)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 27 and 29 August, 17 September and 3 December 1980 by Langan Engineering Associates, Inc., under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Cranberry Lake Dam, a high hazard potential structure, is judged to be in poor overall condition. The spillway is considered seriously inadequate since a flow equivalent to 29 percent of the Probable Maximum Flood (PMF) would cause the dam to be overtopped. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard of loss of life downstream from the dam. To ensure adequacy of the structure, the following actions, as a minimum, are recommended.

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures and studies within three months from the date of approval of this report. Within three months of the consultant's findings remedial measures to ensure spillway adequacy should be initiated. In the interim, a detailed emergency operation plan and warning system should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. The following remedial measures should be initiated within three months from the date of approval of this report:

(1) Investigate the operating condition of the spillway sluice gate and the low level outlet pipe and valve. Repair and modify if necessary.

(2) Remove obstructions and debris in the discharge and downstream channel and provide means to prevent future accumulation of material.

(3) Investigate the backwater effect of the downstream abandoned railroad embankment, modify the outlet facilities or remove the embankment if necessary.

(4) Properly fill the existing animal burrow and provide means to prevent future animal burrowing in the embankment.

c. The following remedial measures should be initiated within six months from the date of approval of this report:

- (1) Repair eroded areas of the embankment.
- (2) Repair dislodged upstream riprap.
- (3) Repair the cracked and spalled concrete of the spillway structure.
- (4) Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundations, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and what modifications may be required to achieve such safety margins.

d. The following remedial actions should be initiated within one year from the date of approval of this report:

- (1) Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.
- (2) Properly remove all trees from the dam embankment and provide adequate filter coverage on the downstream face to prevent any piping which may occur as a result of future root decay.

APPROVED: _____

JAMES G. TOM

Colonel, Corps of Engineers
District Engineer

DATE: _____



IN REPLY REFER TO
NAPEN-N

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

15 MAY 1981

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

Dear Governor Byrne:

This is in reference to our ongoing National Program for Inspection of Non-Federal Dams within the State of New Jersey. Cranberry Lake Dam (Federal I.D. No. NJ00325), a high hazard potential structure, has recently been inspected. The dam is owned by the Morris Canal and Banking Company, and is located on Lubbers Run in Cranberry Lake Township, Sussex County.

Using Corps of Engineers screening criteria, it has been determined that the dam's spillway is seriously inadequate because a flow equivalent to 29 percent of the Probable Maximum Flood would cause the dam to be overtopped. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise, or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard potential to loss of life downstream from the dam. As a result of this UNSAFE determination, it is recommended that the dam's owners take the following measures within 30 days of the date of this letter:

a. Engage the services of a qualified professional consultant to more accurately determine the spillway adequacy by using more detailed and sophisticated hydrologic and hydraulic analyses, and to recommend any remedial measures required to prevent overtopping of the dam.

~~NAPEN~~-N

Honorable Brendan T. Byrne

b. In the interim, a detailed emergency operation plan and downstream warning system should be promptly developed. Also, around the clock surveillance should be provided during periods of unusually heavy precipitation.

A final report on this Phase I Inspection will be forwarded to you within two months.

Sincerely,



JAMES C. TON
Colonel, Corps of Engineers
District Engineer

Copies Furnished:

Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CNO29
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief
Bureau of Flood Plain Regulation
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CNO29
Trenton, NJ 08625

UNSAFE DAM
NATIONAL PROGRAM OF INSPECTION OF DAMS

- a. NAME: Cranberry Lake Dam b. ID NO.: NJ00325 c. LOCATION State: New Jersey, County: Sussex.
- d. HEIGHT: 18 feet e. MAXIMUM IMPOUNDMENT CAPACITY: 3225 ac. ft.
- River or Stream: Lubbers Run
 Nearest D/S City or Town: Cranberry Lake
- f. TYPE: Earthfill. g. OWNER: Morris Canal and Banking Company
- h. DATE GOVERNOR NOTIFIED OF UNSAFE CONDITIONS: 15 May 1981.
- i. URGENCY CATEGORY: High Hazard, UNSAFE, Non-Emergency.
- m. EMERGENCY ACTIONS TAKEN:
Gov. notified of this condition by District Engineer's letter of 15 May 1981.
- n. REMEDIAL ACTIONS TAKEN:
N.J.D.E.P. will notify dam's owner upon receipt of our letter.
- o. REMARKS: Final report, to be issued within six weeks, will have WHITE cover.
- j. DESCRIPTION OF DANGER INVOLVED: High Hazard potential, overtopping and failure of the dam would significantly increase hazard potential to loss of life and property downstream of dam.
- k. RECOMMENDATIONS GIVEN TO GOVERNOR:
Within 30 days of the date of the District Engineer's letter the owner should do the following:
a. Engage the services of a qualified professional consultant to more accurately determine the spillway adequacy by using more detailed and sophisticated hydrologic and hydraulic analyses, and to recommend any remedial measures required to prevent overtopping of the dam.
b. In the interim, a detailed emergency operation plan and downstream warning system should be developed. Also, around the clock surveillance should be provided during periods of unusually heavy precipitation.

T.B. Heverin
T.B. HEVERIN, Coordinator
Dam Inspection Program
U.S.A.E.D., Philadelphia

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM:	CRANBERRY LAKE DAM
ID NUMBER:	FED ID No NJ 00325
STATE LOCATED:	NEW JERSEY
COUNTY LOCATED:	SUSSEX
STREAM:	LUBBERS RUN
RIVER BASIN:	DELAWARE
DATE OF INSPECTION:	AUGUST, SEPTEMBER & DECEMBER 1980

ASSESSMENT OF GENERAL CONDITIONS

Cranberry Lake Dam, classified under high hazard potential category, is in poor overall condition. It is an earth fill dam approximately 18 feet high and 1000 ft long. The dam was reconstructed in 1927. The date of original construction and the extent of reconstruction are not known. Erosion of the embankments has occurred in numerous areas. Riprap has become dislodged and deteriorated in areas along the upstream embankment. The embankments are thickly vegetated with trees and brush. Animal burrow exists on downstream slope of the embankment. The ground at the downstream toe of the south embankment is wet and spongy. There are thin cracks and areas of deteriorating concrete on the spillway structure. The operational condition of the 12-in CIP valve is unknown. The downstream channel is obstructed by the abandoned railroad embankments and the discharge flow is limited by the two outlet pipes through the embankment. There is essentially no available information on the design, construction and operation of the dam. Additional investigation is necessary to adequately evaluate the future performance of the dam.

The spillway capacity as determined by Corps of Engineers Screening criteria is "seriously inadequate". The dam can adequately pass only 28% of the PMF. The spillway adequacy should be determined using more precise and sophisticated methods and procedures.

The following are recommended to be done very soon:

Investigate the operating condition of the spillway sluice gate and the low level outlet pipe and valve; repair and modify if necessary. Remove obstructions and debris in the discharge and downstream channel and provide means to prevent future accumulation of material. Investigate the backwater effect of the downstream abandoned railroad embankment, modify the outlet facilities or remove the embankment if necessary. Properly fill the existing animal burrow and provide means to prevent future animal burrowing in the embankment. The spillway of the dam is "seriously inadequate" as defined in the Corps of Engineers ETL 1110-2-234. The need for and type of mitigating measures should be determined, around-the-clock surveillance during periods of unusually heavy precipitation provided and a warning system established.


The following are recommended to be done soon:

Repair eroded areas of the embankment. Repair dislodged upstream riprap. Repair the cracked and spalled concrete of the spillway structure. Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundations, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and what modifications may be required to achieve such safety margins. Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

The following is recommended to be done in the near future:

Properly remove all trees from the dam embankment and provide adequate filter coverages on the downstream face to prevent any piping which may occur as a result of future root decay.


K. Peter Yu, P.E.



OVERALL VIEW
CRANBERRY LAKE DAM
21 March 1981

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM:	CRANBERRY LAKE DAM
ID NUMBER.	FED ID No NJ 00325
STATE LOCATED:	NEW JERSEY
COUNTY LOCATED:	SUSSEX
STREAM:	LUBBERS RUN
RIVER BASIN:	DELAWARE
DATE OF INSPECTION:	AUGUST, SEPTEMBER & DECEMBER 1980



LANGAN ENGINEERING ASSOCIATES, INC.

Consulting Civil Engineers
990 CLIFTON AVENUE
CLIFTON, NEW JERSEY
201-472-9366



OVERALL VIEW

CRANBERRY LAKE DAM

21 March 1981

CONTENTS

NATIONAL DAM SAFETY REPORT

CRANBERRY LAKE DAM FED ID NO NJ 00325

	<u>PAGE</u>
PREFACE	
SECTION 1 PROJECT INFORMATION	
1.1 <u>General</u>	1
1.2 <u>Project Description</u>	1
1.3 <u>Pertinent Data</u>	2
SECTION 2 ENGINEERING DATA	5
SECTION 3 VISUAL INSPECTION	5
SECTION 4 OPERATIONAL PROCEDURES	5
SECTION 5 HYDRAULIC/HYDROLOGIC	6
SECTION 6 STRUCTURAL STABILITY	6
SECTION 7 ASSESSMENT, RECOMMENDATIONS/ REMEDIAL MEASURES	
7.1 <u>Dam Assessment</u>	7
7.2 <u>Recommendations/Remedial Measures</u>	7
FIGURES	
1. Regional Vicinity Map	
2. Plan & Section of Dam	
3. Section through spillway	
4. Spillway Details	
APPENDICES	
1. Check List, Hydrologic and Hydraulic Data Check List, Visual Inspection Check List, Engineering Data	
2. Photographs	
3. Hydrologic Computations	
4. References	

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

SECTION 1 PROJECT INFORMATION

1.1 General

Authority to perform the Phase I Safety Inspection of Cranberry Lake Dam was received from the State of New Jersey, Department of Environmental Protection, Division of Water Resources by letter dated 12 August 1980. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the US Army Engineers District, Philadelphia.

The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to safety of Cranberry Lake Dam and appurtenances based upon available data and visual inspection, and determine any need for emergency measures and conclude if additional studies, investigations and analyses are necessary and warranted. The assessment is made using screening criteria established in Recommended Guidelines for Safety Inspection of Dams prepared by the Department of Army, Office of the Chief of Engineers. It is not the purpose of the inspection report to imply that a dam meeting or failing to meet the screening criteria is, per se, certainly adequate or inadequate.

1.2 Project Description

a. Description of Dam and Appurtances.

Cranberry Lake Dam is an earthfill dam, approximately 18 ft high and 1000 ft long. It has approximately 2H:1V slopes upstream and downstream. The upstream slope is riprapped with large angular boulders. The downstream slope has no visible riprap and is thickly vegetated with trees and brush. There is a 26 ft concrete broad crested weir spillway located at about the center of the dam. A concrete foot bridge, which is supported by the embankment spillway wing walls, exists over the discharge channel immediately downstream of the spillway. A concrete apron exists in the channel from the spillway to the stream-bed about 25 ft downstream. There is a 2 ft x 2 ft gated sluiceway installed through the weir structure. The gate is located on the upstream side. A 12 inch diameter CI low level outlet pipe is reported to exist under the embankment approximately 44 ft south of the spillway. The valve control is reported to exist in a concrete chamber located on the downstream side of the embankment.

b. Location

Cranberry Lake Dam is located just west of Rt 206 in the Township of Cranberry Lake, Sussex County, New Jersey. It is located at north latitude 40° 57.0' and west longitude 74° 44.3'. A regional vicinity map is given in Figure 1.

c. Size Classification

Cranberry Lake Dam is classified as being "Intermediate" on the basis of its maximum reservoir storage volume of 3225 ac-ft which is less than 50,000 ac-ft but more than 1000 ac-ft. It is classified as "Small" on the basis of its maximum height of 18 feet which is less than 40 feet. The dam is therefore classified as "Intermediate" in size.

d. Hazard Classification

In the National Inventory of Dams, Cranberry Lake Dam has been classified as having "High Hazard Potential" on the basis that failure of the dam would cause excessive property damage to residences downstream and could potentially cause more than a few deaths. Based on the fact that there are houses built on top of the embankment at the south end of the dam, and visual inspections revealed that people utilize the woodland area immediately downstream for recreational purposes year-round, it is recommended to keep the Hazard Potential Classification as "High".

e. Ownership

The Cranberry Lake Dam is owned by the Morris Canal and Banking Company. The NJ DEP, Division of Forests and Parks, Labor and Industry Building, Room 806, Box 1420, Trenton, N. J. 08625 has been appointed Trustee for the lake and dam.

f. Purpose of Dam

The purpose of the dam is presently recreational.

g. Design and Construction History

Cranberry Lake Dam was rebuilt in 1927. The date of original construction and the extent of reconstruction are unknown.

Information concerning the design and construction of the original dam and subsequent reconstruction is unavailable.

h. Normal Operational Procedures

There are no operational procedures for Cranberry Lake Dam as reported by the NJ DEP, Division of Forests and Parks, Lake Hopatcong Regional Office.

1.3 Pertinent Data

a. <u>Drainage Areas</u>	3.02 sq mi
b. <u>Discharge at Dam site</u>	
Maximum flood at dam site	Unknown
Ungated spillway capacity at maximum pool elevation	894 cfs
c. <u>Elevation (ft. above MSL)</u>	
Top dam	763.8
Maximum pool-design surcharge	Unknown

	Recreation pool	763.8 (Assumed to be top of spillway)
	Spillway crest	760.0
	Streambed at centerline of dam	Approximately 746.0 (Estimated)
	Maximum tailwater	Unknown
d.	<u>Reservoir</u>	
	Length of maximum pool	Approx 6600 ft
	Length of recreation pool	Approx 6200 ft
	Length of flood control pool	Approx 6600 ft (Assumed to be maximum pool)
e.	<u>Storage (acre-feet)</u>	
	Recreation pool	2457 ac-ft (Assumed to be spillway crest)
	Design surcharge	Unknown
	Top of dam	3225 ac-ft
f.	<u>Reservoir Surface (acres)</u>	
	Top dam	193 ac
	Maximum pool	193 ac (Assumed to be top of dam)
	Recreation pool	191 ac (Assumed to be spillway crest)
	Spillway crest	191 ac
g.	<u>Dam</u>	
	Type	Earth Embankment
	Length	Approx 1000 ft
	Height	18 ft max.

Side Slopes	2H:1V w/large riprap upstream 2H:1V Downstream
Zoning	Unknown
Impervious Core	Unknown
Cutoff	Unknown
Grout curtain	Unknown
h. <u>Spillway</u>	
Type	Concrete ungated broad crested weir
Length of weir	26 ft total, 24 ft unobstructed
Crest elevation	760.00 MSL
Gates	2 ft x 2 ft sluice gate thru concrete spillway
U/S Channel	Concrete wing walls perpendicular to weir. No up- stream scour pad seen
D/S Channel	Concrete wing walls perpendicular to weir with concrete scour pad
i. <u>Regulating Outlets</u>	A 2 ft x 2 ft sluice gate thru the base of the spillway weir. Inv of sluice approx 755.5 MSL 12" CI pipe thru embankment w/gate valve, located approx 44 ft south of spillway. Discharge inv of pipe El 746.9 Intake inv of pipe unknown

SECTION 2 ENGINEERING DATA

There is no information available concerning design, construction or operation of Cranberry Lake Dam. There are plans and profiles of the existing concrete spillway structure on file with the New Jersey Department of Environmental Protection, Division of Water Resources, Dam Application Number 22-72.

SECTION 3 VISUAL INSPECTION

The embankments of the dam are heavily vegetated with trees and brush. Many trees have trunk diameters greater than 8 inches. Erosion caused by numerous footpaths exist on both the upstream and downstream embankments. An animal burrow hole of about 2 feet in diameter was observed on the downstream slope of the south embankment. There is a berm approximately 10 feet wide existing along a portion of the downstream toe of the south embankment. The toe of the embankment just above the berm has been significantly eroded exposing the roots of the trees in some areas. The downstream area beyond the berm is wet and spongy. The riprap on the upstream face is becoming dislodged in areas. Fill has been placed and houses built on the southernmost end of the embankment.

Thin cracks and minor spalling exist on the concrete of the spillway structure. The sluiceway is partially obstructed by cobbles and gravel. The gate appears rusty as observed through the sluiceway from the downstream side. The discharge channel has accumulated wood, trash and other debris.

The concrete vault housing the control stem of the 12 inch diameter CI low level outlet valve is covered with heavily overgrown brush. It is reported that the operating condition of the valve was checked approx 5 years ago and found to be satisfactory. The present operating condition of the valve is unknown.

The shoreline of the reservoir is comprised of lawns and beaches of private residences, trees and rock outcrops.

The downstream channel is crossed by an abandoned railroad embankment about 200 ft from the spillway. As a result, a pond is formed upstream of the railroad embankment before the detained water discharges downstream by means of two 30-in dia. concrete pipes through the railroad embankment.

SECTION 4 OPERATIONAL PROCEDURES

Maintenance and operation of the Cranberry Lake Dam is by the New Jersey Department of Environmental Protection, Division of Parks and Forests, Lake Hopatcong Region. There are no operational procedures for the dam. No formal warning system appears to be in effect.

SECTION 5 HYDRAULIC/HYDROLOGIC

The hydraulic/hydrologic evaluation is based on a Spillway Design Flood (SDF) equal to the Probable Maximum Flood chosen in accordance with the evaluation guidelines for dams classified as high hazard and intermediate in size. Hydrologic design data for this dam is not available. The PMF has been determined by developing a synthetic hydrograph based on the maximum probable precipitation of 22.3 inches (200 sq mi - 24 hour). The Corps of Engineers has recommended the use of the SCS triangular unit hydrograph with the curvilinear transformation. Hydrologic computations are presented in Appendix 3. The PMF peak inflow determined for the subject watershed is 12751 cfs.

If the backwater effect from the downstream abandoned railroad embankment is not considered, the maximum capacity of the spillway is estimated to be 894 cfs which is significantly less than the SDF. Routing for the 1/2 PMF and PMF indicates the dam will overtop by 1.04 ft and 2.41 ft, respectively. The dam can adequately pass only 28% of the PMF.

Based on the fact that houses are located on the top of the embankment at the south end of the dam, the considerable storage of Cranberry Lake and our knowledge of the degree of overtopping potential, it is our opinion that dam failure from overtopping would significantly increase the hazard potential for excessive loss of life downstream from the dam from that which would exist just before overtopping failure.

The present drawdown structure consists of a 2 x 2 gated sluiceway and a 12" CI pipe with control valve as shown on plans. Drawdown of the reservoir has been evaluated assuming that both drawdown structures are operable. Our calculations indicated that the lake level could be lowered 3 ft in approximately 7 days.

Further evaluation of the hydraulics of the dam should include an analysis of the effect of the backwater from the two-33 reduced to 30-in dia. pipes, which are the only discharge outlets through the railroad embankment located across the downstream channel.

SECTION 6 STRUCTURAL STABILITY

Based on visual observation, no immediate instability appears to exist in Cranberry Lake Dam under normal conditons. However, our visual examination of the dam revealed that erosion has been occurring in numerous areas. The ground beyond the downstream toe of the south embankment is wet and spongy. The embankments are thickly vegetated with trees and brush. The spillway discharge is seriously interferred by the downstream abandoned railroad embankment. A rapid drawdown on the downstream face of the dam will result in the event of a failure of the railroad embankment caused by excessive water retained in the low area between the two embankments.

No design or construction data is available for Cranberry Lake Dam, consequently analytical analyses of the dam cannot be made without gross assumptions concerning the properties of the materials used in the dam construction and foundation materials.

There are no operating procedures or records for Cranberry Lake Dam.

Cranberry Lake Dam is located in Seismic Zone I of the Seismic Zone Map of Contiguous States. As no information is available concerning the engineering properties of the foundation and dam materials, the degree of stability of the dam and appurtenances under more severe stress conditions than normal and its future performance cannot be evaluated without further investigation.

SECTION 7 ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment

Cranberry Lake Dam is in poor overall condition. It is an earth fill dam approximately 18 feet high and 1000 ft long. The dam was reconstructed in 1927. The date of original construction and the extent of reconstruction are not known. Erosion of the embankments has occurred in numerous areas. Riprap has become dislodged and deteriorated in areas along the upstream embankment. The embankments are thickly vegetated with trees and brush. Animal burrow exists on downstream slope of the embankment. The ground at the downstream toe of the south embankment is wet and spongy. There are thin cracks and areas of deteriorating concrete on the spillway structure. The operational condition of the 12-in CIP valve is unknown. The downstream channel is obstructed by the abandoned railroad embankments and the discharge flow is limited by the two outlet pipes through the embankment. There is essentially no available information on the design, construction and operation of the dam. Additional investigation is necessary to adequately evaluate the future performance of the dam.

The spillway capacity as determined by Corps of Engineers Screening criteria is "seriously inadequate". The dam can adequately pass only 28% of the PMF. The spillway adequacy should be determined using more precise and sophisticated methods and procedures.

7.2 Recommendations/Remedial Measures

The following are recommended to be done very soon:

1. Investigate the operating condition of the spillway sluice gate and the low level outlet pipe and valve. Repair and modify if necessary.
2. Remove obstructions and debris in the discharge and downstream channel and provide means to prevent future accumulation of material.
3. Investigate the backwater effect of the downstream abandoned railroad embankment, modify the outlet facilities or remove the embankment if necessary.

4. Properly fill the existing animal burrow and provide means to prevent future animal burrowing in the embankment.
5. The spillway of the dam is "seriously inadequate" as defined in the Corps of Engineers ETL 1110-2-234. The need for and type of mitigating measures should be determined, around-the-clock surveillance during periods of unusually heavy precipitation provided and a warning system established.


The following are recommended to be done soon:

1. Repair eroded areas of the embankment.
2. Repair dislodged upstream riprap.
3. Repair the cracked and spalled concrete of the spillway structure.
4. Perform additional investigation to determine seepage conditions through and under the dam, the engineering properties of the dam and foundations, and whether or not conventional safety margins exist under more severe stress conditions than those observed during our inspection, and what modifications may be required to achieve such safety margins.
5. Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.


The following is recommended to be done in the near future:

1. Properly remove all trees from the dam embankment and provide adequate filter coverages on the downstream face to prevent any piping which may occur as a result of future root decay.

FIGURES




BY _____ DATE _____ REGIONAL VICINITY MAP JOB NO. 80145
 CKD _____ DATE _____ CRANBERRY LAKE FIG 1



TYPICAL SECTION


CRANBERRY



PLAN

ERRY LAKE

SPILLWAY SECTION
RAILS - FIG. No. 2



NOTES:

1. SKETCHES BASED ON VISUAL INSPECTION AND INFORMATION FROM "CONSTRUCTION PLAN FOR INSTALLATION OF SLUICE GATE IN SPILLWAY AT CRANBERRY LAKE IN SUSSEX COUNTY, N.J." BY MILLER & MCGIFFERT, INC. AND DATED APRIL, 1959.
2. DATUM - M.S.L.
TOP OF SPILLWAY WAS USED AS BM AT EL 760.0 FOR FIELD SPOT CHECK.

PLAN AND SECTION OF DAM
CRANBERRY LAKE DAM

CRANBERRY LAKE

SUSSEX COUNTY, N.J.

LANGAN ENGINEERING ASSOCIATES, INC.

990 CLIFTON AVENUE CLIFTON, N.J. 07013

DRN. BY: T.C.

SCALE: N.T.S.

JOB No. 80145


CK'D. BY: P.Y.

DATE: 2-19-61

FIG. No. 2

AN

12



SECTION THRU SPI
AND DOWNSTREAM CH

764

759

FORMER LACKAWANNA R.R. EMBANKMENT
TRACKS REMOVED 7/80 - 8/80

754

BALLAST

SOUTH SHORE ROAD

EL. 748.6

749

EL. 748.7

PAVEMENT

2-33" PIPES

EL. 746.66

INV. 5'LY PIPE
EL. 745.60

2-30"
PIPES

INV. EL. 744.06

744

NOTES:

1. SKETCHES ADAPTED FROM CONSTRUCTION PLAN FOR INSTALLATION OF SLUCE GATE IN SPILLWAY AT CRANBERRY LAKE IN SUSSEX COUNTY, N.J. BY MILLER & Mc GIFFERT, INC. AND DATED APRIL, 1959.
2. DATUM - M.S.L.

U. SPILLWAY
AM CHANNEL

SECTION

CRANBERRY LAKE DAM

CRANBERRY LAKE SUSSEX COUNTY, N.J.

LANGAN ENGINEERING ASSOCIATES, INC.

990 CLIFTON AVENUE CLIFTON, N.J. 07013

DRN. BY: R.D.


SCALE: N.T.S.

JOB No. 80145

CK'D. BY: V.U.

DATE: 9-5-80

FIG. No. 3




EL. 75


PLAN VIEW @ SPILLWAY

NOTES:

1. SKETCH
STRUCT
OF SLL
CRANE
COUNT
ME GIP
APRIL
2. DATUM



SECTION 'A-A'



SECTION 'B-B'

- NOTES:
1. SKETCHES ADAPTED FROM "CONSTRUCTION PLAN FOR INSTALLATION OF SLUCE GATE IN SPILLWAY AT CRANBERRY LAKE IN SUSSEX COUNTY, N.J." BY MILLER & Mc GIFFORT, INC. AND DATED ON APRIL, 1959.
 2. DATUM - M.S.L.

SPILLWAY DETAILS CRANBERRY LAKE DAM

CRANBERRY LAKE

SUSSEX COUNTY, N.J.

LANGAN ENGINEERING ASSOCIATES, INC.

990 CLIFTON AVENUE CLIFTON, N.J. 07013

DRN. BY: R.D.

SCALE: N.T.S.

JOB No. 80145

CK'D. BY: V.U.

DATE: 9-9-80

FIG. No. 4

APPENDIX 1

CRANBERRY LAKE DAM

1. CHECK LIST - HYDROLOGIC AND HYDRAULIC DATA
2. CHECK LIST - VISUAL INSPECTION
3. CHECK LIST - ENGINEERING DATA

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 3.02 sq. mi., woods & forest land, avg 2.2% slope

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 760 (2457 ac-ft)

ELEVATION TOP MAXIMUM POOL (STORAGE CAPACITY): 763.8 (3225 ac-ft)

ELEVATION MAXIMUM DESIGN POOL: 763.8 (Assumes top of dam)

ELEVATION TOP DAM: 763.8

CREST: Spillway

- a. Elevation 760
- b. Type broad crested trapezoidal weir
- c. Width 3'
- d. Length 24' (effective)
- e. Location Spillover Approximately center of dam
- f. Number and Type of Gates 1 - 2' x 2' sluice gate through weir

OUTLET WORKS: _____

- a. Type 2 x 2 sluice gate
- b. Location 8 ft North of South wing wall
- c. Entrance inverts 755.6
- d. Exit inverts 755.6
- e. Emergency draindown facilities 12" CIP @ inv 746.9 (assumed elev.)

HYDROMETEOROLOGICAL GAGES: None known

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE: 894 cfs @ 763.8

Check List
Visual Inspection
Phase 1

Name Dam CRANBERRY LAKE DAM County SUSSEX State NJ Coordinators NJ DEP

Date(s) Inspection SEE BELOW Weather CLEAR (8/27/80) Temperature LOW 90's F (8/27/80)

Pool Elevation at Time of Inspection 759 M.S.L. APPROX (8/27/80) Tailwater at Time of Inspection NONE M.S.L.

Inspection Personnel:

R. W. GREENE 8/27/80

D. J. LEARY 9/17/80 & 12/3/80

K. PETER YU 8/29/80 & 12/3/80

V. URBAN 8/27/80

R. W. GREENE Recorder

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	NONE OBSERVED	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	NO CRACKS OBSERVED. GROUND AT TOE OF SOUTH EMBANKMENT WET AND SPONGY.	
SLOUGHING OR EROSION OF EMBANKMENT AND ADJUTANT SLOPES	EROSION CAUSED BY NUMEROUS FOOTPATHS ON BOTH UP & DOWN STREAM EMBANKMENTS. EROSION ALONG DOWNSTREAM TOE OF SOUTH EMBANKMENT JUST ABOVE BERM.	PROPERLY REPAIR ERODED AREA.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	CREST RUNS ROUGHLY SOUTH & NORTH WITH SLIGHT REVERSE CURVE APPROXIMATELY 1000'. NO OBSERVABLE EVIDENCE THAT MOVEMENT HAS OCCURRED.	
RIPRAP FAILURES	AREAS OF DISLODGED RIPRAP ALONG TOP OF UPSTREAM EMBANKMENT.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	<p>EMBANKMENT NORTH AND SOUTH OF SPILLWAY HEAVILY VEGETATED WITH TREES & BRUSH.</p> <p>ANIMAL HOLE ABOUT 2-FT DIA. ON DOWNSTREAM SLOPE OF SOUTH EMBANKMENT</p>	<p>PROPERLY FILL ANIMAL HOLE AND REMOVE TREES AND ROOTS.</p>
<p>JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM</p>	<p>NO SIGN OF CRACKS, SEEPAGE OR MOVEMENT SEEN AT ANY JUNCTIONS.</p>	
<p>ANY NOTICEABLE SEEPAGE</p>	<p>THERE ARE AREAS OF PONDED WATER AND SOFT SPONGY GROUND ALONG THE TOE OF THE SOUTH DOWNSTREAM EMBANKMENT.</p>	
<p>STAFF GAGE AND RECORDER</p>	<p>NONE OBSERVED.</p>	
<p>DRAINS</p>	<p>NONE OBSERVABLE.</p>	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	SLUICeway CONCRETE HAS NO CRACK & SPALL. 12" CI PIPE AND GATE INACCESSIBLE AND NOT INSPECTED.	TWO OUTLET WORKS 1. 2'x2' SLUICeway THROUGH SPILLWAY WEIR STRUCTURE 2. 12" GATED CI PIPE UNDER SOUTH EMBANKMENT. CLEAR ACCESS, PERFORM INSPECTION.
INTAKE STRUCTURE	NONE. INTAKE OF PIPE BELOW POOL ELEVATION.	NOT VISIBLE.
OUTLET STRUCTURE	CONCRETE VAULT HOUSING VALVE CONTROL FOR 12" CI PIPE. COVER ON VAULT. VAULT HEAVILY OVERGROWN WITH BRUSH.	OPERATING CONDITION OF VALVE UNKNOWN. REMOVE VEGETATION, PERFORM INSPECTION.
OUTLET CHANNEL	OUTLETS INTO POND DOWNSTREAM OF SPILLWAY. CHANNEL UNOBSTRUCTED.	
EMERGENCY GATE	2' x 2' SLUICE GATE APPEARED RUSTY AS VIEWED THROUGH SLUICeway FROM DOWNSTREAM SIDE.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	NO APPARENT DEFECTS OBSERVED.	
APPROACH CHANNEL	VERTICAL CONCRETE WING WALLS EXTENDING 4 FT UPSTREAM PERPENDICULAR TO WEIR. THE CONCRETE HAS A FEW THIN CRACKS AND SMALL AREAS OF SPALLING. CHANNEL UNOBSTRUCTED.	REPAIR CONCRETE.
DISCHARGE CHANNEL	CONCRETE APRON PAD AND VERTICAL WING WALLS EXTENDING APPROX 26 FT DOWNSTREAM. TRASH AND DEBRIS HAVE ACCUMULATED ON THE APRON. ROCKS, BOTTLES, CANS, SMALL BRANCHES, ETC. THIN CRACKS AND SPALLING OF CONCRETE WING WALLS.	DEBRIS SHOULD BE REMOVED. REPAIR CONCRETE.
BRIDGE AND PIERS	CONCRETE FOOT BRIDGE OVER SPILLWAY APPROX 6 1/2 FT WIDE BETWEEN PARAPETS, PARALLEL TO WEIR, APPROXIMATELY 3 FT ABOVE WEIR, SUPPORTED BY CENTER PIER AND WING WALLS.	

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	GENTLE, LOW RELIEF AROUND RESERVOIR, VARIABLE SLOPES. SLOPES COMPRISED OF LAWNS, WOODED AREAS AND ROCK OUTCROPS.	
SEDIMENTATION	COARSE GRAVEL, COBBLES & BOULDERS UPSTREAM OF SPILLWAY. NO FINES SEEN.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	CHANNEL PARTIALLY OBSTRUCTED BY TREES & MISCELLANEOUS DEBRIS BEYOND SPILLWAY APRON. IT IS FURTHER OBSTRUCTED BY RR EMBANKMENT APPROX 200 FT DOWNSTREAM AND DISCHARGE FLOW LIMITED BY 2 3-FT DIA. OUTLET PIPES.	RR ABANDONED, TRACKS REMOVED. INVESTIGATE THE BACKWATER AFFECT OF THE DOWNSTREAM EMBANKMENT. MODIFY THE OUTLET FACILITIES OR REMOVE THE EMBANKMENT IF NECESSARY.
SLOPES	GENTLE, HEAVILY WOODED.	
APPROXIMATE NO. OF HOMES AND POPULATION	NONE VISIBLE DOWNSTREAM. APPROXIMATELY 6 HOMES BUILT ON SOUTH END OF SOUTH EMBANKMENT.	

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	NO INFORMATION AVAILABLE
REGIONAL VICINITY MAP	SEE FIGURE 1
CONSTRUCTION HISTORY	NO INFORMATION AVAILABLE
TYPICAL SECTIONS OF DAM	NO INFORMATION AVAILABLE
HYDROLOGIC/HYDRAULIC DATA	NO INFORMATION AVAILABLE
OUTLETS - PLAN	12 INCH CI LOW LEVEL OUTLET WITH VALVE
- DETAILS	NO INFORMATION AVAILABLE
- CONSTRAINTS	NO INFORMATION AVAILABLE
- DISCHARGE RATINGS	NO INFORMATION AVAILABLE
RAINFALL/RESERVOIR RECORDS	NO INFORMATION AVAILABLE

ITEM	REMARKS
------	---------

DESIGN REPORTS	NO INFORMATION AVAILABLE
----------------	--------------------------

GEOLOGY REPORTS	NO INFORMATION AVAILABLE
-----------------	--------------------------

DESIGN COMPUTATIONS	
HYDROLOGY & HYDRAULICS	NO INFORMATION AVAILABLE
DAM STABILITY	
SEEPAGE STUDIES	

MATERIALS INVESTIGATIONS	
BORING RECORDS	NO INFORMATION AVAILABLE
LABORATORY	
FIELD	

POST-CONSTRUCTION SURVEYS OF DAM	Inspection Report Cranberry Lake Dam and Spillway 21 September 1972
----------------------------------	--

By: Storch Engineers
Florham Park, N.J.

Source: NJ DEP
Div. of Water Resources
Dam Application No 22-72

BORROW SOURCES.	NO INFORMATION AVAILABLE
-----------------	--------------------------

ITEM	REMARKS
MONITORING SYSTEMS	NO INFORMATION AVAILABLE
MODIFICATIONS	CONSTRUCTION OF A 2 FT X 2 FT SLUICE AND GATE THROUGH THE SPILLWAY WEIR
HIGH POOL RECORDS	NO INFORMATION AVAILABLE
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	NO INFORMATION AVAILABLE
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	NONE REPORTED BY NJ DEP DIVISION OF LAKES AND FORESTS LAKE HOPATCONG REGION
MAINTENANCE OPERATION RECORDS	NO INFORMATION AVAILABLE

REMARKS

ITEM

SPILLWAY PLAN	SHOWN IN CONSTRUCTION PLAN FOR INSTALLATION OF SLUICE GATE IN SPILLWAY AT CRANBERRY LAKE, SUSSEX COUNTY, N.J.	PREPARED BY: MILLER & MCGIFFERT, INC., ENGINEERS 484 BLOOMFIELD AVE MONTCLAIR, NJ APRIL 1959	SOURCE NJ DEP DEPT. OF WATER RESOURCES DAM APPLICATION NO 22-7:
SECTIONS	PREPARED FOR CRANBERRY LAKE COMMUNITY CLUB		
DETAILS			

OPERATING EQUIPMENT PLANS & DETAILS

2 FT X 2 FT SPILLWAY SLUICE GATE - SEE SPILLWAY PLAN
12 IN DIA. CI LOW LEVEL OUTLET - NO INFORMATION AVAILABLE

APPENDIX 2
PHOTOGRAPHS



View of north upstream embankment
taken from spillway bridge looking
north.

27 August 1980




View of south embankment taken
from spillway bridge looking south.

27 August 1980



North approach channel wing
wall and weir crest.

27 August 1980



South approach channel wing
wall, weir crest and sluice
gate control.

27 August 1980



North spillway wing wall
and scour pad.

27 August 1980



South spillway wing wall
and scour pad.

27 August 1980



Downstream face of spillway
looking upstream.

27 August 1980



Downstream channel and pond
looking east from bridge
over spillway.

27 August 1980

APPENDIX 3
HYDROLOGICAL COMPUTATIONS

HYDROLOGICAL COMPUTATIONSCRANBERRY LAKE DAMA. Location: Sussex County, N.J., Lubbers RunB. Drainage area: 3.02 sq. mi (1927 acres)C. Lake area: 191 acresD. Classification: Size - intermediate
Hazard - highE. Spillway Design Flood: PMPF. PMP

1. Dam located in Zone 6 (near zone 1 boundary)

PMP = 22.3 inches (for 200 sq. mi, 24 hr,
'all season envelope')*2. PMF must be adjusted by a factor of 0.80**
to account for basin size under 10 sq. mi

% Factor for ≤ 10 sq. mi			
Duration	Zone 1	Zone 6	Avg
0-6	111	113	112
0-12	123	123	123
0-24	133	132	132
0-48	142	142	142

* HMR #33

** Page 48 "Design of Small Dams"


BY KAWDATE 8-17-81Cranberry Lake DamJOB NO. 80145CKD PyDATE 2/17/81SHEET NO. 1 OF 1

G. DETERMINE TIME OF CONCENTRATION

Majority of the watercourse is stream or channel flow

1. Estimate T_c based on average velocity and length

$$\begin{aligned} \text{Ave slope } (Y) &= \frac{1140 - 760}{10000} \\ &= 3.8\% \end{aligned}$$



From Fig 3-1, SCS TR-55
for grassed waterway, at 3.8% slope
velocity ≈ 3 fps

$$T_c = \frac{10,000}{3 \times 60 \times 60} = 0.93 \text{ hrs.}$$

$$L = 0.6 T_c = 0.56 \text{ hrs.}$$

2. Estimate T_c from curve number method

From Table 2-2 SCS TR-55

for soil group C (County soil survey - Sussex, N.J.)
use $CN = 80$

$$S = \frac{1000}{CN} - 10 = \frac{1000}{80} - 10 = 2.5$$

$$\begin{aligned} \text{Lag time } L &= \frac{L^{0.8} (S+1)^{0.7}}{1900 (Y)^{0.5}} \quad \text{Eq. 3-2 TR-55} \\ &= \frac{10000^{0.8} (3.5)^{0.7}}{1900 (3.8)^{0.5}} = 1.03 \text{ hr.} \end{aligned}$$

use $L = 0.8 \text{ hrs}$

BY PJ
CKD RUG

DATE 7/12/81
DATE 2/19/81

Cranberry

JOB NO. 40145

SHEET NO. 2 OF

SPILLWAY CAPACITY

The spillway is similar to a broad crested weir therefore the equation $Q = CLH^{3/2}$ (where L = Length and H = head (ft) above the crest)

shall be used.

The crest of the weir which has a width of 3 feet is at elevation 760. The top of the weir is at the bottom of the walkway bridge (el. 763.1). Above this elevation, the flow becomes orifice flow and is therefore calculated using $Q = CA\sqrt{2gh}$

The top of the dam is at elevation 763.8 and weir flow is assumed for its length of 969 ft. Between elevations 763.8 and 765.4, the concrete parapet on the spillway becomes an obstruction; however, above 765.4 it will act as a weir.

See plans & sections for geometry of the dam & spillway.

A 2x2 sluice gate is blocked with rubble, ∴ for this analysis it is assumed inoperable.

BY NU

DATE

9-15-80 Cranbury

JOB NO. _____

CKD py

DATE

4/7/81SHEET NO. 3


OF _____

ELEV.	2x2 SLUICE	SPILLWAY		EMBANKMENT		PARAPET		L=31' W=7.6'		NOTES
		H (ft)	C	H (ft)	C	H (ft)	C	H (ft)	C	
755.6		Weir Flow: $Q = CLH^{3/2}$								Bottom of 2x2 Sluice Gate
756.6		Orifice Flow: $Q = CA\sqrt{2gh}$								
757.6										
760		0	—	0	0					Top of Spillway
760.5		.5	2.63	22.1						22
761		1.0	2.65	64						64
762		2.0	2.72	185						185
763		3.0	2.92	364						364
763.1		3.1	2.93	384						384
763.8	GATE IS IMPERMEABLE IN CLOSED POSITION. RUBBLE BEHIND GATE	* becomes orifice 2.25	.85	894	0					894
764		2.45	"	933	2	2.49	216			1149
765		3.45	"	1107	1.2	2.69	3426			4533
765.4		3.85	"	1169	1.6	2.64	5177	0	—	6346
766		4.95	"	1257	2.2	2.64	8348	.6	2.7	9644
767		5.45	"	1391	3.2	2.64	14644	1.6	2.645	16201
768		6.45	"	1513	4.2	2.64	22019	2.6	2.65	23876

A = $(3.64 \times 12) \times 2 = 87.36$ C values for weir flow obtained from table 5-3, King & Brater, Hbt. of Hyd.

C values for orifice flow from table 33, Small Dams

SUMMARY OF SPILLWAY CAPACITY



BY KA DATE 8/15/81 CRABBEY
 CKD Py DATE 7/17/81 Spillway Rating Curve

JOB NO. 80125
 SHEET NO. 5 OF 5

Reservoir Storage Capacity

Assume a linear distribution for the area of the lake with elevation. Start at a zero storage at the crest of the spillway (El 760)

Area of Lake = 191 ac

Length of equivalent square = 2887.4 ft

Take average side slope: 1 V : 2 H

∴ for every foot of water above the crest of the spillway the length of the equivalent square increases by: $2 \times 2 \times 1 = 4'$

Elevation (ft)	H (ft)	Length of Equiv. Square (ft)	Area of Lake (acres)
760	0	2887.4	191
761	1	2888.4	191.5
762	2	2892.4	192.0
763	3	2896.4	192.6
763.8	3.8	2899.6	193.0
764	4	2900.4	193.1
765	5	2904.4	193.6
765.19	5.19	2905.2	193.8
766	6	2908.4	194.2
767	7	2912.4	194.7
768	8	2916.4	195.3

Storage Capacity vs. elevation is calculated by HEC 1

BY Ku DATE 9-19-80 Cranberry Lake
CKD py DATE 2/17/81

JOB NO. 80195
SHEET NO. 6 OF

SUMMARY OF HYDROGRAPH & FLOOD ROUTING


- 1) Hydrograph & Routing calculated using HEC-1DB
- 2) PMF for Cranberry Lake is 12751 cfs (routed to 10992 cfs).
- 3) Routing of PMF indicates that the dam will overtop by 2.41 ft.
- 4) Routing of $\frac{1}{2}$ PMF indicates that the dam will overtop by 1.04 ft.

BY VLS DATE 8-15-80 Cranberry Lake
 CKD Py DATE 2/17/81

JOB NO. 10195
 SHEET NO. 7 OF 7

OVERTOPPING POTENTIAL

- 1) Various % of PMF have been routed using HEC-1DB
- 2) Plot peak outflow vs. % PMF



- 3) Dam overtops at elev. 763.8 with $Q = 894$
 \therefore dam can pass approx 28 % of PMF.

BY RM DATE 8/7/80 Cranberry Lake JOB NO. 80125
 CKD. fy DATE 7/1/81 SHEET NO. 8 OF

DRAWDOWN ANALYSIS1) Outlet Structures

There presently exists a 2'x2' sluice gate in the weir of the spillway. It is presently covered with rocks & debris which would cause it to be inoperable. A 12" cast iron pipe & blowoff is located south of the spillway in the south embankment. A manhole & outlet from the pipe are located on the shore of the lower pond at the toe of the embankment. The structure is covered with brush and its operating condition is unknown.

2.) Outlet Capacity - Sluice

invert of 2'x2' sluice = 755.6 & elev = 756.6

Spillway crest = 760

Apply equation for orifice flow $Q = CA\sqrt{2gh}$

where $C = .85$ for square edged entrance.

water elev. (ft)	Head (ft)	Q (cfs)
760	4.4	57
759	3.4	50
758	2.4	42
757	1.4	32
756	.4	17
755.6	0	0

BY Ma DATE 9-23-88 Cranberry Lake JOB NO. 80195
 CKD. By DATE 9/6/91 draw down SHEET NO. 9 OF

3) Outlet Capacity - 12" CI Pipe

a) M.V. assumed at 746.90
 & elev = 747.4 (L=145 ft ±)

b) Spillway Crest elev. 763.74

c) Pipe capacity based on $Q = C_p H^{1/2}$
 where $C_p = A_p \sqrt{\frac{2g}{1+K_m+K_pL}}$

using $n = .015 = .025$ (use .025), $K_p = .1157$ (NEH Sect. 5 ES-42)

$A_p = .785 f^2$, $K_m = .90$

$C_p = 1.46$, $Q = 1.46 H^{1/2}$

Water elev (ft)	head (ft)	Q (cfs)
760	12.6	5.2
759	11.6	4.9
758	10.6	4.7
757	9.6	4.5
756	8.6	4.3
755.6	8.2	4.2
752	4.6	3.1
750	2.6	2.4
748	.6	1.1
746.9	0	0

BY LM DATE 9-22-86 Cronberry JOB NO. 80145
 CKD mg DATE 3/6/11 drawdown SHEET NO. 10 OF

Elev. (ft)	$Q_{2 \times 2}$ (cfs)	$Q_{12' \times 18'}$ (cfs)	ΣQ (cfs)
760	57	5	62
759	50	5	55
758	42	5	47
757	32	4	36
756	17	4	21
755.6	0	4	4
752	—	3	3
750	—	2	2
748	—	1	1
746.9	—	0	0

OUTLET CAPACITY SUMMARY

BY KU DATE 7/23/80 Crosberry JOB NO. 20145
 CKD. Pg DATE 3/6/81 drawn SHEET NO. 11 OF

Storage Capacity

- a) Use method of equivalent square as done in "Reservoir Storage Capacity"
- b) Area at spillway crest elev 760 = 191 acres and has an equivalent square length of 2884.4 (2:1 slopes)

Water Elevation (ft)	Length of Equiv Sq (ft)	Area (ac)	ΔH (ft)	Increment Volume (ac-ft)	Volume
760	2884.4	191			
759	2880.4	190.5	1	191	2457
758	2876.4	189.9	1	190	2266
757	2872.4	189.4	1	189	2076
756	2868.4	188.9	1	189	1887
755.6	2866.8	188.7	.4	76	1698
752	2852.4	186.8	3.6	676	1622
750	2844.4	185.7	2	373	946
748	2836.4	184.7	2	370	573
746.9	2832	184.1	1.1	203	203

BY ruDATE 9/6/66Cranberry LakeJOB NO. 80/95CKD BDATE 3/6/67drawdownSHEET NO. 12OF

DRAWDOWN CALCULATION


Elev. (ft)	Q _{out} (cfs)	Q _{avg} (cfs)	Q _{net} * (cfs)	Storage (ac-ft)	Δt (hr)	ΣΔt (hr)	ΣΔt (days)
760	62	59	53	191	43.6	43.6	1.8
759	55	51	45	190	51.1	94.7	3.9
758	47	42	36	189	63.5	158.2	6.6
757	36	29	23	189	99.4	257.6	10.7
756	21	13	7	76	131.4	389	16.2
755.6	4		**	676	-		-
752	3		**	373	-		-
750	2		**	370	-		-
748	1		**	203	-		-
746.9	0						

* Q_{net} = Q_{avg} - Q_{in} Assume 2 cfs/sgmt ** into > outflow not consid.

$$Q_{in} = 2(3.02) = 6 \text{ cfs}$$

$$Q_{net} = Q_{avg} - 6$$

Lake can be drawdown 3 ft in about 7 day



<p>Drainage Basin</p> <p>Cranberry Dam</p>	<p>Map Source USGS</p> <p>Stanhope Scale 1"=2000'</p>	<p>Proj No. 80145</p> <p>Sheet _____ of _____</p>
--	---	---

HEC-1

CRANBERRY LAKE DAM

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE: 81/02/18.
 TIME: 09.25.09.

CRANBERRY LAKE DAM (00325)
 INFLOW HYDROGRAPHY AND ROUTING
 N J DAM INSPECTIONS

JOB SPECIFICATION									
NO	NMR	MIN	IDAY	HR	MIN	MTRC	IPLY	IPRT	INSTAN
290	0	.10	0	0	0	0	0	0	0
			JOPER	NMT	LROPT	IRACE			
			3	0	0	0			

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	LAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA									
IHYDG	IUMG	IAREA	SHAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	2	3.01	0.00	3.01	.80	0.000	0	0	0

PRECIP DATA

SPFE	PHS	R6	R12	R24	R48	R72	R96
0.00	22.30	112.00	123.00	132.00	142.00	0.00	0.00

LOSS DATA

LROPT	STKR	DLTKR	RTIOL	ERAIN	STKRS	RTIOL	STRTL	UNSTL	ALSHX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.15	0.00	0.00

UNIT HYDROGRAPH DATA
 TC= 0.00 LAG=.80

STRID= -2.00 ORCSN= 0.00 RTIDR= 1.00

UNIT HYDROGRAPH 26 END OF PERIOD ORDINATES, TC= 0.00 HOURS, LAG=.80
 152. 466. 980. 1449. 1637. 1598. 1389. 1101. 761. 556.
 414. 309. 225. 166. 121. 88. 65. 48. 36. 26.
 19. 15. 11. 8. 5. 2.

END-OF-PERIOD FLOW													
MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP 0	NO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP 0
1.01	.10	1	.00	0.00	.00	6.	1.02	.20	146	.02	0.00	.02	6.
1.01	.20	2	.00	0.00	.00	6.	1.02	.30	147	.02	0.00	.02	6.
1.01	.30	3	.00	0.00	.00	6.	1.02	.40	148	.02	0.00	.02	6.
1.01	.40	4	.00	0.00	.00	6.	1.02	.50	149	.02	0.00	.02	6.
1.01	.50	5	.00	0.00	.00	6.	1.02	1.00	150	.02	0.00	.02	6.
1.01	1.00	6	.00	0.00	.00	6.	1.02	1.10	151	.02	0.00	.02	6.
1.01	1.10	7	.00	0.00	.00	6.	1.02	1.20	152	.02	0.00	.02	6.

THIS PAGE IS BEST QUALITY PRACTICES
 FROM COPY FURNISHED TO BDC

1.01	1.20	8	0.00	0.00	.00	5.	1.02	1.30	153	.02	0.00	.02	6.
1.01	1.30	9	.00	0.00	.00	6.	1.02	1.40	154	.02	0.00	.02	6.
1.01	1.40	10	.00	0.00	.00	6.	1.02	1.50	155	.02	0.00	.02	6.
1.01	1.50	11	.00	0.00	.00	6.	1.02	2.00	156	.02	0.00	.02	6.
1.01	2.00	12	.00	0.00	.00	6.	1.02	2.10	157	.02	0.00	.02	6.
1.01	2.10	13	.00	0.00	.00	6.	1.02	2.20	158	.02	0.00	.02	6.
1.01	2.20	14	.00	0.00	.00	6.	1.02	2.30	159	.02	0.00	.02	6.
1.01	2.30	15	.00	0.00	.00	6.	1.02	2.40	160	.02	0.00	.02	6.
1.01	2.40	16	.00	0.00	.00	6.	1.02	2.50	161	.02	0.00	.02	6.
1.01	2.50	17	.00	0.00	.00	6.	1.02	3.00	162	.02	0.00	.02	6.
1.01	3.00	18	.00	0.00	.00	6.	1.02	3.10	163	.02	0.00	.02	6.
1.01	3.10	19	.00	0.00	.00	6.	1.02	3.20	164	.02	0.00	.02	6.
1.01	3.20	20	.00	0.00	.00	6.	1.02	3.30	165	.02	0.00	.02	6.
1.01	3.30	21	.00	0.00	.00	6.	1.02	3.40	166	.02	0.00	.02	6.
1.01	3.40	22	.00	0.00	.00	6.	1.02	3.50	167	.02	0.00	.02	6.
1.01	3.50	23	.00	0.00	.00	6.	1.02	4.00	168	.02	0.00	.02	6.
1.01	4.00	24	.00	0.00	.00	6.	1.02	4.10	169	.02	0.00	.02	6.
1.01	4.10	25	.00	0.00	.00	6.	1.02	4.20	170	.02	0.00	.02	6.
1.01	4.20	26	.00	0.00	.00	6.	1.02	4.30	171	.02	0.00	.02	6.
1.01	4.30	27	.00	0.00	.00	6.	1.02	4.40	172	.02	0.00	.02	6.
1.01	4.40	28	.00	0.00	.00	6.	1.02	4.50	173	.02	0.00	.02	6.
1.01	4.50	29	.00	0.00	.00	6.	1.02	5.00	174	.02	0.00	.02	6.
1.01	5.00	30	.00	0.00	.00	6.	1.02	5.10	175	.02	0.00	.02	6.
1.01	5.10	31	.00	0.00	.00	6.	1.02	5.20	176	.02	0.00	.02	6.
1.01	5.20	32	.00	0.00	.00	6.	1.02	5.30	177	.02	0.00	.02	6.
1.01	5.30	33	.00	0.00	.00	6.	1.02	5.40	178	.02	0.00	.02	6.
1.01	5.40	34	.00	0.00	.00	6.	1.02	5.50	179	.02	0.00	.02	6.
1.01	5.50	35	.00	0.00	.00	6.	1.02	6.00	180	.02	0.00	.02	6.
1.01	6.00	36	.00	0.00	.00	6.	1.02	6.10	181	.03	0.03	.03	10.
1.01	6.10	37	.00	0.00	.00	6.	1.02	6.20	182	.05	.03	.03	24.
1.01	6.20	38	.00	0.00	.00	6.	1.02	6.30	183	.05	.03	.03	53.
1.01	6.30	39	.00	0.00	.00	6.	1.02	6.40	184	.05	.03	.03	96.
1.01	6.40	40	.00	0.00	.00	6.	1.02	6.50	185	.05	.03	.03	144.
1.01	6.50	41	.00	0.00	.00	6.	1.02	7.00	186	.05	.03	.03	191.
1.01	7.00	42	.00	0.00	.00	6.	1.02	7.10	187	.05	.03	.03	232.
1.01	7.10	43	.00	0.00	.00	6.	1.02	7.20	188	.05	.03	.03	265.
1.01	7.20	44											

THIS PAGE IS BEST QUALITY REPRODUCTION
FROM COPY FURNISHED TO EDC

1.01	12.20	.03	0.00	.03	6.	1.02	12.50	219	.33	.31	.03	795.
1.01	12.30	.03	0.00	.03	6.	1.02	12.40	220	.33	.31	.03	1198.
1.01	12.40	.03	0.00	.03	6.	1.02	12.50	221	.33	.31	.03	1654.
1.01	12.50	.03	0.00	.03	6.	1.02	13.00	222	.33	.31	.03	2099.
1.01	13.00	.03	0.00	.03	6.	1.02	13.10	223	.40	.37	.03	2496.
1.01	13.10	.03	0.00	.03	6.	1.02	13.20	224	.40	.37	.03	2834.
1.01	13.20	.03	0.00	.03	6.	1.02	13.30	225	.40	.37	.03	3111.
1.01	13.30	.03	0.00	.03	6.	1.02	13.40	226	.40	.37	.03	3363.
1.01	13.40	.03	0.00	.03	6.	1.02	13.50	227	.40	.37	.03	3587.
1.01	13.50	.03	0.00	.03	6.	1.02	14.00	228	.40	.37	.03	3780.
1.01	14.00	.03	0.00	.03	6.	1.02	14.10	229	.50	.47	.03	3950.
1.01	14.10	.04	0.00	.04	6.	1.02	14.20	230	.50	.47	.03	4116.
1.01	14.20	.04	0.00	.04	6.	1.02	14.30	231	.50	.47	.03	4299.
1.01	14.30	.04	0.00	.04	6.	1.02	14.40	232	.50	.47	.03	4505.
1.01	14.40	.04	0.00	.04	6.	1.02	14.50	233	.50	.47	.03	4714.
1.01	14.50	.04	0.00	.04	6.	1.02	15.00	234	.50	.47	.03	4908.
1.01	15.00	.04	0.00	.04	6.	1.02	15.10	235	.46	.43	.03	5065.
1.01	15.10	.03	0.00	.03	6.	1.02	15.20	236	.76	.73	.03	5219.
1.01	15.20	.06	0.00	.06	6.	1.02	15.30	237	1.37	1.34	.03	5499.
1.01	15.30	.10	0.00	.10	6.	1.02	15.40	238	3.42	3.39	.03	6392.
1.01	15.40	.26	.19	.07	35.	1.02	15.50	239	.99	.96	.03	7991.
1.01	15.50	.07	.05	.03	103.	1.02	16.00	240	.61	.58	.03	10156.
1.01	16.00	.05	.02	.03	220.	1.02	16.10	241	.47	.44	.03	11991.
1.01	16.10	.04	.01	.03	343.	1.02	16.20	242	.47	.44	.03	12751.
1.01	16.20	.04	.01	.03	418.	1.02	16.30	243	.47	.44	.03	12519.
1.01	16.30	.04	.01	.03	440.	1.02	16.40	244	.47	.44	.03	11542.
1.01	16.40	.04	.01	.03	417.	1.02	16.50	245	.47	.44	.03	10207.
1.01	16.50	.04	.01	.03	368.	1.02	17.00	246	.47	.44	.03	8794.
1.01	17.00	.04	.01	.03	300.	1.02	17.10	247	.37	.34	.03	7798.
1.01	17.10	.03	.00	.03	251.	1.02	17.20	248	.37	.34	.03	7059.
1.01	17.20	.03	.00	.03	215.	1.02	17.30	249	.37	.34	.03	6450.
1.01	17.30	.03	.00	.03	184.	1.02	17.40	250	.37	.34	.03	5913.
1.01	17.40	.03	.00	.03	154.	1.02	17.50	251	.37	.34	.03	5467.
1.01	17.50	.03	.00	.03	128.	1.02	18.00	252	.37	.34	.03	5096.
1.01	18.00	.03	.00	.03	106.	1.02	18.10	253	.03	.00	.03	4750.
1.01	18.10	.00	0.00	.00	88.	1.02	18.20	254	.03	.00	.03	4370.
1.01	18.20	.00	0.00	.00	73.	1.02	18.30	255	.03	.00	.03	3880.
1.01	18.30	.00	0.00	.00	61.	1.02	18.40	256	.03	.00	.03	3272.
1.01	18.40	.00	0.00	.00	50.	1.02	18.50	257	.03	.00	.03	2630.
1.01	18.50	.00	0.00	.00	40.	1.02	19.00	258	.03	.00	.03	2025.
1.01	19.00	.00	0.00	.00	32.	1.02	19.10	259	.03	.00	.03	1509.
1.01	19.10	.00	0.00	.00	25.	1.02	19.20	260	.03	.00	.03	1100.
1.01	19.20	.00	0.00	.00	20.	1.02	19.30	261	.03	.00	.03	813.
1.01	19.30	.00	0.00	.00	16.	1.02	19.40	262	.03	.00	.03	600.
1.01	19.40	.00	0.00	.00	13.	1.02	19.50	263	.03	.00	.03	440.
1.01	19.50	.00	0.00	.00	11.	1.02	20.00	264	.03	.00	.03	324.
1.01	20.00	.00	0.00	.00	9.	1.02	20.10	265	.03	.00	.03	243.
1.01	20.10	.00	0.00	.00	8.	1.02	20.20	266	.03	.00	.03	183.
1.01	20.20	.00	0.00	.00	8.	1.02	20.30	267	.03	.00	.03	140.
1.01	20.30	.00	0.00	.00	7.	1.02	20.40	268	.03	.00	.03	109.
1.01	20.40	.00	0.00	.00	7.	1.02	20.50	269	.03	.00	.03	85.
1.01	20.50	.00	0.00	.00	7.	1.02	21.00	270	.03	.00	.03	68.
1.01	21.00	.00	0.00	.00	6.	1.02	21.10	271	.03	.00	.03	56.
1.01	21.10	.00	0.00	.00	6.	1.02	21.20	272	.03	.00	.03	47.
1.01	21.20	.00	0.00	.00	6.	1.02	21.30	273	.03	.00	.03	40.
1.01	21.30	.00	0.00	.00	6.	1.02	21.40	274	.03	.00	.03	35.
1.01	21.40	.00	0.00	.00	6.	1.02	21.50	275	.03	.00	.03	31.
1.01	21.50	.00	0.00	.00	6.	1.02	22.00	276	.03	.00	.03	29.
1.01	22.00	.00	0.00	.00	6.	1.02	22.10	277	.03	.00	.03	27.
1.01	22.10	.00	0.00	.00	6.	1.02	22.20	278	.03	.00	.03	27.
1.01	22.20	.00	0.00	.00	6.	1.02	22.30	279	.03	.00	.03	27.
1.01	22.30	.00	0.00	.00	6.	1.02	22.40	280	.03	.00	.03	27.
1.01	22.40	.00	0.00	.00	6.	1.02	22.50	281	.03	.00	.03	27.
1.01	22.50	.00	0.00	.00	6.	1.02	23.00	282	.03	.00	.03	27.
1.01	23.00	.00	0.00	.00	6.	1.02	23.10	283	.03	.00	.03	27.
1.01	23.10	.00	0.00	.00	6.	1.02	23.20	284	.03	.00	.03	27.

THIS PAGE IS BEST QUALITY MATERIAL
 FROM DUFF FORTIFIED TO 800

1.01	23.20	140	.00	0.00	.00	6.	1.02	23.30	285	.03	.00	.03	27.
1.01	23.30	141	.00	0.00	.00	6.	1.02	23.40	286	.03	.00	.03	27.
1.01	23.40	142	.00	0.00	.00	6.	1.02	23.50	287	.03	.00	.03	27.
1.01	23.50	143	.00	0.00	.00	6.	1.03	0.00	288	.03	.00	.03	27.
1.02	0.00	144	.00	0.00	.00	6.	1.03	.10	289	0.00	0.00	0.00	26.
1.02	.10	145	.02	0.00	.02	6.	1.03	.20	290	0.00	0.00	0.00	25.
SUM 25.33 20.55 4.79 241013.													
(643.)(522.)(122.)(6824.73)													

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
12751.	5904.	1640.	831.	240997.
CFS				
361.	167.	46.	24.	6824.
INCHES	18.25	20.27	20.69	30.69
MM	463.43	514.94	525.49	525.49
AC-FT	2927.	3233.	3320.	3320.
THOUS CU M	3611.	4012.	4095.	4095.

HYDROGRAPH ROUTING

ROUTING COMPUTATIONS

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JFRT	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	1	0	0
CLOSS	AVG	ROUTING DATA						
0.0	0.000	1	0	0	0	0	0	0
LAG AMSKK X TSK STORA ISPRAT								
1	0	0	0.000	0.000	0.000	0.	-1	

STAGE	760.00	760.50	761.00	762.00	763.00	763.10	763.80	764.00	765.00	765.40
FLOW	0.00	22.00	44.00	185.00	364.00	384.00	894.00	1149.00	4533.00	6346.00
SURFACE AREA	191.	192.	192.	193.	193.	194.	194.	195.	195.	
CAPACITY	0.	191.	383.	575.	768.	961.	1155.	1350.	1545.	
ELEVATION	760.	761.	762.	763.	764.	765.	766.	767.	768.	

CREL	SPUID	COQM	EXPM	ELEV	COOL	CAREA	EXPL
760.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
DAM DATA							
TOPEL	COOD	EXPD	DAMWID				
763.8	0.0	0.0	0.0				

NO.2A	HR.MM	PERIOD	HOURS	INFLOW	OUTFLOW	STORAGE	STAGE
1.01	.10	1	.17	6.	0.	0.	760.0
1.01	.20	2	.33	6.	0.	0.	760.0
1.01	.30	3	.50	6.	0.	0.	760.0
1.01	.40	4	.67	6.	0.	0.	760.0
1.01	.50	5	.83	6.	0.	0.	760.0
1.01	1.00	6	1.00	6.	0.	0.	760.0
1.01	1.10	7	1.17	4.	0.	1.	760.0

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO BBC

1.01	1.20	8	1.33	6.	0.	1.	760.0
1.01	1.30	9	1.50	6.	0.	1.	760.0
1.01	1.40	10	1.67	6.	0.	1.	760.0
1.01	1.50	11	1.83	6.	0.	1.	760.0
1.01	2.00	12	2.00	6.	0.	1.	760.0
1.01	2.10	13	2.17	6.	0.	1.	760.0
1.01	2.20	14	2.33	6.	0.	1.	760.0
1.01	2.30	15	2.50	6.	0.	1.	760.0
1.01	2.40	16	2.67	6.	0.	1.	760.0
1.01	2.50	17	2.83	6.	0.	1.	760.0
1.01	3.00	18	3.00	6.	0.	1.	760.0
1.01	3.10	19	3.17	6.	0.	2.	760.0
1.01	3.20	20	3.33	6.	0.	2.	760.0
1.01	3.30	21	3.50	6.	0.	2.	760.0
1.01	3.40	22	3.67	6.	0.	2.	760.0
1.01	3.50	23	3.83	6.	0.	2.	760.0
1.01	4.00	24	4.00	6.	0.	2.	760.0
1.01	4.10	25	4.17	6.	0.	2.	760.0
1.01	4.20	26	4.33	6.	0.	2.	760.0
1.01	4.30	27	4.50	6.	0.	2.	760.0
1.01	4.40	28	4.67	6.	1.	2.	760.0
1.01	4.50	29	4.83	6.	1.	2.	760.0
1.01	5.00	30	5.00	6.	1.	2.	760.0
1.01	5.10	31	5.17	6.	1.	2.	760.0
1.01	5.20	32	5.33	6.	1.	3.	760.0
1.01	5.30	33	5.50	6.	1.	3.	760.0
1.01	5.40	34	5.67	6.	1.	3.	760.0
1.01	5.50	35	5.83	6.	1.	3.	760.0
1.01	6.00	36	6.00	6.	1.	3.	760.0
1.01	6.10	37	6.17	6.	1.	3.	760.0
1.01	6.20	38	6.33	6.	1.	3.	760.0
1.01	6.30	39	6.50	6.	1.	3.	760.0
1.01	6.40	40	6.67	6.	1.	3.	760.0
1.01	6.50	41	6.83	6.	1.	3.	760.0
1.01	7.00	42	7.00	6.	1.	3.	760.0
1.01	7.10	43	7.17	6.	1.	3.	760.0
1.01	7.20	44	7.33	6.	1.	3.	760.0
1.01	7.30	45	7.50	6.	1.	3.	760.0
1.01	7.40	46	7.67	6.	1.	4.	760.0
1.01	7.50	47	7.83	6.	1.	4.	760.0
1.01	8.00	48	8.00	6.	1.	4.	760.0
1.01	8.10	49	8.17	6.	1.	4.	760.0
1.01	8.20	50	8.33	6.	1.	4.	760.0
1.01	8.30	51	8.50	6.	1.	4.	760.0
1.01	8.40	52	8.67	6.	1.	4.	760.0
1.01	8.50	53	8.83	6.	1.	4.	760.0
1.01	9.00	54	9.00	6.	1.	4.	760.0
1.01	9.10	55	9.17	6.	1.	4.	760.0
1.01	9.20	56	9.33	6.	1.	4.	760.0
1.01	9.30	57	9.50	6.	1.	4.	760.0
1.01	9.40	58	9.67	6.	1.	4.	760.0
1.01	9.50	59	9.83	6.	1.	4.	760.0
1.01	10.00	60	10.00	6.	1.	5.	760.0
1.01	10.10	61	10.17	6.	1.	5.	760.0
1.01	10.20	62	10.33	6.	1.	5.	760.0
1.01	10.30	63	10.50	6.	1.	5.	760.0
1.01	10.40	64	10.67	6.	1.	5.	760.0
1.01	10.50	65	10.83	6.	1.	5.	760.0
1.01	11.00	66	11.00	6.	1.	5.	760.0
1.01	11.10	67	11.17	6.	1.	5.	760.0
1.01	11.20	68	11.33	6.	1.	5.	760.0
1.01	11.30	69	11.50	6.	1.	5.	760.0
1.01	11.40	70	11.67	6.	1.	5.	760.0
1.01	11.50	71	11.83	6.	1.	5.	760.0
1.01	12.00	72	12.00	4.	1.	5.	760.0
1.01	12.10	73	12.17	4.	1.	5.	760.0

THIS PAGE IS BEST QUALITY PRINT-OUT
FROM COPY FURNISHED TO DDC

1.01	12.20	74	12.33	6.	1.	5.	760.0
1.01	12.30	75	12.50	6.	1.	6.	760.0
1.01	12.40	76	12.67	6.	1.	6.	760.0
1.01	12.50	77	12.83	6.	1.	6.	760.0
1.01	13.00	78	13.00	6.	1.	6.	760.0
1.01	13.10	79	13.17	6.	1.	6.	760.0
1.01	13.20	80	13.33	6.	1.	6.	760.0
1.01	13.30	81	13.50	6.	1.	6.	760.0
1.01	13.40	82	13.67	6.	1.	6.	760.0
1.01	13.50	83	13.83	6.	1.	6.	760.0
1.01	14.00	84	14.00	6.	1.	6.	760.0
1.01	14.10	85	14.17	6.	1.	6.	760.0
1.01	14.20	86	14.33	6.	1.	6.	760.0
1.01	14.30	87	14.50	6.	1.	6.	760.0
1.01	14.40	88	14.67	6.	1.	6.	760.0
1.01	14.50	89	14.83	6.	1.	6.	760.0
1.01	15.00	90	15.00	6.	1.	6.	760.0
1.01	15.10	91	15.17	6.	2.	7.	760.0
1.01	15.20	92	15.33	6.	2.	7.	760.0
1.01	15.30	93	15.50	6.	2.	7.	760.0
1.01	15.40	94	15.67	35.	2.	7.	760.0
1.01	15.50	95	15.83	103.	2.	8.	760.0
1.01	16.00	96	16.00	220.	2.	10.	760.1
1.01	16.10	97	16.17	343.	3.	14.	760.1
1.01	16.20	98	16.33	418.	4.	19.	760.1
1.01	16.30	99	16.50	440.	6.	25.	760.1
1.01	16.40	100	16.67	417.	7.	31.	760.2
1.01	16.50	101	16.83	368.	8.	36.	760.2
1.01	17.00	102	17.00	300.	9.	41.	760.2
1.01	17.10	103	17.17	251.	10.	44.	760.2
1.01	17.20	104	17.33	215.	11.	47.	760.2
1.01	17.30	105	17.50	184.	11.	50.	760.3
1.01	17.40	106	17.67	154.	12.	52.	760.3
1.01	17.50	107	17.83	128.	12.	54.	760.3
1.01	18.00	108	18.00	106.	13.	55.	760.3
1.01	18.10	109	18.17	88.	13.	56.	760.3
1.01	18.20	110	18.33	73.	13.	57.	760.3
1.01	18.30	111	18.50	61.	13.	58.	760.3
1.01	18.40	112	18.67	50.	14.	59.	760.3
1.01	18.50	113	18.83	40.	14.	59.	760.3
1.01	19.00	114	19.00	32.	14.	59.	760.3
1.01	19.10	115	19.17	25.	14.	60.	760.3
1.01	19.20	116	19.33	20.	14.	60.	760.3
1.01	19.30	117	19.50	16.	14.	60.	760.3
1.01	19.40	118	19.67	13.	14.	60.	760.3
1.01	19.50	119	19.83	11.	14.	60.	760.3
1.01	20.00	120	20.00	9.	14.	60.	760.3
1.01	20.10	121	20.17	8.	14.	60.	760.3
1.01	20.20	122	20.33	8.	14.	60.	760.3
1.01	20.30	123	20.50	7.	14.	59.	760.3
1.01	20.40	124	20.67	7.	14.	59.	760.3
1.01	20.50	125	20.83	7.	14.	59.	760.3
1.01	21.00	126	21.00	6.	14.	59.	760.3
1.01	21.10	127	21.17	6.	14.	59.	760.3
1.01	21.20	128	21.33	6.	14.	59.	760.3
1.01	21.30	129	21.50	6.	14.	59.	760.3
1.01	21.40	130	21.67	6.	14.	59.	760.3
1.01	21.50	131	21.83	6.	14.	59.	760.3
1.01	22.00	132	22.00	6.	13.	59.	760.3
1.01	22.10	133	22.17	6.	13.	58.	760.3
1.01	22.20	134	22.33	6.	13.	58.	760.3
1.01	22.30	135	22.50	6.	13.	58.	760.3
1.01	22.40	136	22.67	6.	13.	58.	760.3
1.01	22.50	137	22.83	6.	13.	58.	760.3
1.01	23.00	138	23.00	4.	13.	58.	760.3
1.01	23.10	139	23.17	4.	13.	58.	760.3

THIS PAGE IS NOT QUALITY TRANSLATED
FROM OUR FAVORITE TV SHOW

1.01	23.20	140	23.33	6.	13.	58.	760.3
1.01	23.30	141	23.50	6.	13.	58.	760.3
1.01	23.40	142	23.67	6.	13.	58.	760.3
1.01	23.50	143	23.83	6.	13.	57.	760.3
1.02	0.00	144	24.00	6.	13.	57.	760.3
1.02	.10	145	24.17	6.	13.	57.	760.3
1.02	.20	146	24.33	6.	13.	57.	760.3
1.02	.30	147	24.50	6.	13.	57.	760.3
1.02	.40	148	24.67	6.	13.	57.	760.3
1.02	.50	149	24.83	6.	13.	57.	760.3
1.02	1.00	150	25.00	6.	13.	57.	760.3
1.02	1.10	151	25.17	6.	13.	57.	760.3
1.02	1.20	152	25.33	6.	13.	57.	760.3
1.02	1.30	153	25.50	6.	13.	56.	760.3
1.02	1.40	154	25.67	6.	13.	56.	760.3
1.02	1.50	155	25.83	6.	13.	56.	760.3
1.02	2.00	156	26.00	6.	13.	56.	760.3
1.02	2.10	157	26.17	6.	13.	56.	760.3
1.02	2.20	158	26.33	6.	13.	56.	760.3
1.02	2.30	159	26.50	6.	13.	56.	760.3
1.02	2.40	160	26.67	6.	13.	56.	760.3
1.02	2.50	161	26.83	6.	13.	56.	760.3
1.02	3.00	162	27.00	6.	13.	56.	760.3
1.02	3.10	163	27.17	6.	13.	56.	760.3
1.02	3.20	164	27.33	6.	13.	55.	760.3
1.02	3.30	165	27.50	6.	13.	55.	760.3
1.02	3.40	166	27.67	6.	13.	55.	760.3
1.02	3.50	167	27.83	6.	13.	55.	760.3
1.02	4.00	168	28.00	6.	13.	55.	760.3
1.02	4.10	169	28.17	6.	13.	55.	760.3
1.02	4.20	170	28.33	6.	13.	55.	760.3
1.02	4.30	171	28.50	6.	13.	55.	760.3
1.02	4.40	172	28.67	6.	13.	55.	760.3
1.02	4.50	173	28.83	6.	13.	55.	760.3
1.02	5.00	174	29.00	6.	13.	55.	760.3
1.02	5.10	175	29.17	6.	13.	54.	760.3
1.02	5.20	176	29.33	6.	13.	54.	760.3
1.02	5.30	177	29.50	6.	12.	54.	760.3
1.02	5.40	178	29.67	6.	12.	54.	760.3
1.02	5.50	179	29.83	6.	12.	54.	760.3
1.02	6.00	180	30.00	6.	12.	54.	760.3
1.02	6.10	181	30.17	10.	12.	54.	760.3
1.02	6.20	182	30.33	24.	13.	54.	760.3
1.02	6.30	183	30.50	53.	13.	54.	760.3
1.02	6.40	184	30.67	96.	13.	55.	760.3
1.02	6.50	185	30.83	144.	13.	57.	760.3
1.02	7.00	186	31.00	191.	14.	59.	760.3
1.02	7.10	187	31.17	232.	14.	62.	760.3
1.02	7.20	188	31.33	265.	15.	65.	760.3
1.02	7.30	189	31.50	287.	16.	68.	760.4
1.02	7.40	190	31.67	304.	17.	72.	760.4
1.02	7.50	191	31.83	316.	18.	76.	760.4
1.02	8.00	192	32.00	325.	19.	80.	760.4
1.02	8.10	193	32.17	332.	19.	85.	760.4
1.02	8.20	194	32.33	337.	20.	89.	760.5
1.02	8.30	195	32.50	340.	21.	93.	760.5
1.02	8.40	196	32.67	343.	23.	98.	760.5
1.02	8.50	197	32.83	345.	25.	102.	760.5
1.02	9.00	198	33.00	346.	27.	107.	760.6
1.02	9.10	199	33.17	347.	29.	111.	760.6

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY 100-100000

1.02	10.20	206	34.33	350.	42.	141.	760.7
1.02	10.30	207	34.50	350.	44.	145.	760.8
1.02	10.40	208	34.67	350.	46.	150.	760.8
1.02	10.50	209	34.83	350.	48.	154.	760.8
1.02	11.00	210	35.00	350.	49.	158.	760.8
1.02	11.10	211	35.17	350.	51.	162.	760.8
1.02	11.20	212	35.33	350.	53.	166.	760.9
1.02	11.30	213	35.50	350.	55.	170.	760.9
1.02	11.40	214	35.67	350.	57.	174.	760.9
1.02	11.50	215	35.83	350.	58.	178.	760.9
1.02	12.00	216	36.00	350.	60.	182.	761.0
1.02	12.10	217	36.17	392.	62.	187.	761.0
1.02	12.20	218	36.33	522.	64.	192.	761.0
1.02	12.30	219	36.50	795.	70.	200.	761.0
1.02	12.40	220	36.67	1198.	78.	213.	761.1
1.02	12.50	221	36.83	1654.	89.	231.	761.2
1.02	13.00	222	37.00	2099.	105.	256.	761.3
1.02	13.10	223	37.17	2496.	124.	286.	761.5
1.02	13.20	224	37.33	2834.	144.	321.	761.7
1.02	13.30	225	37.50	3111.	170.	360.	761.9
1.02	13.40	226	37.67	3363.	202.	402.	762.1
1.02	13.50	227	37.83	3587.	244.	446.	762.3
1.02	14.00	228	38.00	3780.	288.	493.	762.6
1.02	14.10	229	38.17	3950.	333.	542.	762.8
1.02	14.20	230	38.33	4116.	382.	593.	763.1
1.02	14.30	231	38.50	4299.	572.	644.	763.4
1.02	14.40	232	38.67	4505.	767.	696.	763.6
1.02	14.50	233	38.83	4714.	1010.	747.	763.9
1.02	15.00	234	39.00	4908.	1623.	795.	764.1
1.02	15.10	235	39.17	5065.	2347.	837.	764.4
1.02	15.20	236	39.33	5219.	2948.	871.	764.5
1.02	15.30	237	39.50	5499.	3466.	901.	764.7
1.02	15.40	238	39.67	6392.	3999.	931.	764.8
1.02	15.50	239	39.83	7991.	4730.	970.	765.0
1.02	16.00	240	40.00	10156.	5936.	1021.	765.3
1.02	16.10	241	40.17	11991.	7541.	1081.	765.6
1.02	16.20	242	40.33	12751.	9118.	1137.	765.9
1.02	16.30	243	40.50	12519.	10363.	1177.	766.1
1.02	16.40	244	40.67	11542.	10992.	1195.	766.2
1.02	16.50	245	40.83	10207.	10947.	1194.	766.2
1.02	17.00	246	41.00	8794.	10402.	1178.	766.1
1.02	17.10	247	41.17	7798.	9612.	1154.	766.0
1.02	17.20	248	41.33	7059.	8900.	1129.	765.9
1.02	17.30	249	41.50	6450.	8200.	1104.	765.7
1.02	17.40	250	41.67	5913.	7541.	1081.	765.6
1.02	17.50	251	41.83	5467.	6937.	1060.	765.5
1.02	18.00	252	42.00	5096.	6396.	1041.	765.4
1.02	18.10	253	42.17	4750.	5980.	1023.	765.3
1.02	18.20	254	42.33	4370.	5587.	1007.	765.2
1.02	18.30	255	42.50	3880.	5181.	989.	765.1
1.02	18.40	256	42.67	3272.	4736.	970.	765.0
1.02	18.50	257	42.83	2630.	4307.	949.	764.9
1.02	19.00	258	43.00	2025.	3882.	924.	764.8
1.02	19.10	259	43.17	1509.	3427.	898.	764.7
1.02	19.20	260	43.33	1100.	2971.	872.	764.5
1.02	19.30	261	43.50	813.	2538.	847.	764.4
1.02	19.40	262	43.67	600.	2144.	825.	764.3
1.02	19.50	263	43.83	440.	1794.	805.	764.2
1.02	20.00	264	44.00	324.	1490.	788.	764.1
1.02	20.10	265	44.17	243.	1230.	773.	764.0
1.02	20.20	266	44.33	183.	1094.	760.	764.0
1.02	20.30	267	44.50	140.	1013.	748.	763.9
1.02	20.40	268	44.67	109.	936.	736.	763.8
1.02	20.50	269	44.83	85.	876.	725.	763.8
1.02	21.00	270	45.00	48.	816.	714.	763.7
1.02	21.10	271	45.17	76.	797.	704.	763.7

THIS PAGE IS OF LOW QUALITY
FROM COPY FORWARDED TO ERM

1.02	21.20	272	45.33	47.	759.	694.	763.6
1.02	21.30	273	45.50	40.	723.	684.	763.6
1.02	21.40	274	45.67	35.	688.	675.	763.5
1.02	21.50	275	45.83	31.	655.	666.	763.5
1.02	22.00	276	46.00	29.	633.	658.	763.4
1.02	22.10	277	46.17	27.	593.	650.	763.4
1.02	22.20	278	46.33	27.	565.	642.	763.3
1.02	22.30	279	46.50	27.	537.	635.	763.3
1.02	22.40	280	46.67	27.	511.	628.	763.3
1.02	22.50	281	46.83	27.	487.	622.	763.2
1.02	23.00	282	47.00	27.	463.	616.	763.2
1.02	23.10	283	47.17	27.	441.	610.	763.2
1.02	23.20	284	47.33	27.	420.	604.	763.1
1.02	23.30	285	47.50	27.	400.	599.	763.1
1.02	23.40	286	47.67	27.	383.	594.	763.1
1.02	23.50	287	47.83	27.	378.	589.	763.1
1.03	0.00	288	48.00	27.	373.	584.	763.0
1.03	.10	289	48.17	26.	368.	579.	763.0
1.03	.20	290	48.33	25.	363.	575.	763.0

PEAK OUTFLOW IS 10992. AT TIME 40.67 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	10992.	5035.	1379.	687.	199328.
CMS	311.	143.	39.	19.	5644.
INCHES		15.56	17.05	17.11	
MM		395.22	433.12	434.63	
AC-FT		2497.	2736.	2746.	
THOUS CU M		3079.	3375.	3387.	

RUNOFF SUMMARY, AVERAGE FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES(SQUARE KILOMETERS)

HYDROGRAPH AT	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
1	12751.	5904.	1640.	831.	3.01
(361.08)	(46.44)	(7.80)
ROUTED TO	2	10992.	1379.	687.	3.01
(311.25)	(39.06)	(7.80)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 760.00 0. 0.	SPILLWAY CREST 760.00 0. 0.	TOP OF DAM 763.80 730. 894.	DURATION OVER TOP HOURS	MAXIMUM OUTFLOW CFS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	10992.	4.00	40.67	0.00
0.00	766.21	2.41	1193.	10992.				

FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1970


```

EEEEEEEEEE CCCCCCCC HH 00000000
EEEEEEEEEE CCCCCCCC HH 00000000
EE CC CC HH 000 000
EE CC CC HH 00 00
EE CC CC HH 00 00
EE CC CC HH 00 00
EE CC CC HH 00 00
EEEEEEEEEE CC HHHHHHHHHH 00 00
EEEEEEEEEE CC HHHHHHHHHH 00 00
EE CC CC HH 00 00
EE CC CC HH 00 00
EE CC CC HH 00 00
EE CCC CC HH 000 000
EEEEEEEEEE CCCCCCCC HH 00000000
EEEEEEEEEE CCCCCCCC HH 00000000

```

```

*****
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 26 FEB 79
*****

```

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

```

1
RUNOFF HYDROGRAPH AT 1
ROUTE HYDROGRAPH TO 2
END OF NETWORK

```

```

*****
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 26 FEB 79
*****

```

```

RUN DATE 81/02/18.
TIME 12.24.46.

```

CRANBERRY LAKE DAM (00323)
INFLOW HYDROGRAPHY AND ROUTING
N J DAM INSPECTIONS

JOB SPECIFICATION		METRIC		IPRT		NSTAN	
NO	NMR	IDAY	IMIN	IPRT	IPRT	NSTAN	NSTAN
290	0	10	0	0	4	0	0
		JOPER	NWT	LROPT	IRACE		
		0	0	0	0		

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRTIO= 5 LRTIO= 1

RTIOS= .10 .20 .30 .40 .50

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JFLT	JFRT	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INHYDG	IJMG	YAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	2	3.01	0.00	3.01	.80	0.000	0	0	0

PRECIP DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	22.30	112.00	123.00	132.00	142.00	0.00	0.00

LOSS DATA

LROPT	STRKR	DLTKR	RTIOL	ERAIN	SIRKS	RTIOK	SIRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.15	0.00	0.00

UNIT HYDROGRAPH DATA

TC= 0.00 LAG= .80

RECESSION DATA

STRTO= -2.00 GRCSN= 0.00 KTIOR= 1.00

END-OF-PERIOD FLOW

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
0							SUM	25.33	20.55	4.79	241013.		
								(643.)	(522.)	(122.)	(6824.73)		

HYDROGRAPH ROUTING

ROUTING COMPUTATIONS

ISTAQ	ICOMP	IECON	ITAPE	JFLT	JFRT	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	CLOSS	AVG	IRES	ISAME	IOPT	IPMP	LSTR
0.0	0.000	0.00	1	0	0	0	0

LAG

MSPTS	MSIDL	LAG	AMSKK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	0.	-1

STAGE	760.00	760.50	761.00	762.00	763.00	763.10	763.80	764.00	765.00	765.40
	766.00	767.00	768.00							

FLOW	0.00	22.00	44.00	185.00	364.00	384.00	894.00	1149.00	4533.00	6346.00
	9644.00	16201.00	23074.00							

SURFACE AREA	191.	192.	193.	194.	194.	194.	195.	195.
--------------	------	------	------	------	------	------	------	------

THIS PAGE IS BEST QUALITY PRACTICE
FROM COPY FURNISHED TO BDC

CAPACITY= 0. 191. 383. 575. 768. 961. 1135. 1350. 1545.
ELEVATION= 760. 761. 762. 763. 764. 765. 766. 767. 768.
CREL SPWID COOL EXPW ELEV COOL CAREA EXPL
760.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA
TOPEL COCD EXPD DAMWID
763.8 0.0 0.0 0.

PEAK OUTFLOW IS 128. AT TIME 43.33 HOURS
PEAK OUTFLOW IS 351. AT TIME 43.17 HOURS
PEAK OUTFLOW IS 1088. AT TIME 42.50 HOURS
PEAK OUTFLOW IS 2549. AT TIME 41.50 HOURS
PEAK OUTFLOW IS 3988. AT TIME 41.17 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIO 5
.10 .20 .30 .40 .50
HYDROGRAPH AT 1 3.01 1 1275. 2550. 3825. 5101. 6376.
(7.80) (36.11) (72.22) (108.32) (144.43) (180.54)
ROUTED TO 2 3.01 1 128. 351. 1088. 2549. 3988.
(7.80) (3.61) (9.93) (30.82) (72.17) (112.93)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1
ELEVATION INITIAL VALUE SPILLWAY CREST TOP OF DAM
STORAGE 760.00 760.00 763.80
OUTFLOW 0. 0. 730.
0. 0. 894.
RATIO OF MAXIMUM MAXIMUM MAXIMUM MAXIMUM MAXIMUM MAXIMUM
PHF RESERVOIR DEPTH OVER DAM STORAGE OUTFLOW DURATION OVER TUP TIME OF
W.S.ELEV OVER DAM AC-FT CFS HOURS HOURS FAILURE
.10 761.52 0.00 292. 128. 0.00 0.00 43.33 0.00
.20 762.92 0.00 561. 351. 0.00 0.00 43.17 0.00
.30 763.98 .15 759. 1088. 0.00 0.00 42.50 0.00
.40 764.41 .41 848. 2549. 3.33 41.50 41.50 0.00
.50 764.84 .84 894. 3988. 41.17 41.17 41.17 0.00

APPENDIX 4
REFERENCES

APPENDIX 4

REFERENCES CRANBERRY LAKE DAM

1. Brater, Ernest F. and Kings, Horace W., Handbook of Hydraulics 5th Edition, McGraw-Hill Book Company 1963.
2. United States Dept. of Agriculture, Soil Conservation Service, Somerset, N.J., Urban Hydrology for Small Watersheds, Technical Release No 55 Jan 1975.
3. United States Dept. of Commerce Weather Bureau, April 1956, Hydrometeorological Report #33, Washington, D.C.
4. United States Dept. of Interior, Bureau of Reclamation Design of Small Dams, Second Edition 1973, Revised print 1977.
5. United States Dept. of Agriculture, Soil Conservation Service, Soil Survey of Sussex County and Morris County, August 1975.
6. United States Army Corps of Engineers, Flood Hydrograph Package (HEC-1), Davis, Calif., Sept 1978.
7. United States Dept. of Agriculture, SCS, A Method for Estimating Volume and Rate of Runoff in Small Watersheds SCS-TP-149, Revised April 1973.
8. United States Army Corps of Engineers, Recommended Guidelines for Safety Inspection of Dams, Washington, D.C.
9. Sauls, G. A., Additional Hydrology and Hydraulics Guidance, 12 Sept 1978.
10. Storch Engineers, Inspection Report, Cranberry Lake Dam and Spillway, 21 Sept 1972, NJ DEP Dam Application File 22-72.
11. Construction Plans for Installation of Sluice Gate in Spillway at Cranberry Lake, Sussex County, New Jersey, Prepared by Miller & McGiffert, Inc., April 1959.

DATE
FILMED
-8